


GARRISON ENGINEER (N) MES MAMUN MIL STATION

SAFETY CERTIFICATE

1. It is to certify that the vidyalaya building, boundary wall and staff quarter of PM SHRI, KV No.3, Mamun Military Station, Pathankot were ^{visually} inspected by the undersigned and found in good condition for the smooth functioning.
2. It may please be noted that no testing has been carried out to check the structural soundness/stability of the Vidyalaya building, boundary wall and staff quarters of PM SHRI, KV No.3, Mamun Military Station, Pathankot.



(Jatinder Kumar)
(AE (Civ))
AGE B/R-II

COUNTERSIGNED

K Agrawal, IDSE
EE (SG)
Garrison Engineer

प्रिन्सिपल/प्राचार्य/Principal
वे.वि.नं.-3/के.वि.क्र.3/K.V.No.3.
मामून कैंट/मामून कैंट/Mamoon Cantt.
पथानकोट/Pathankot